Contact No. 272Image: Second seco

Changes to UB & UB2 Pushbuttons; LB, UB & UB2 Iluminated Pushbuttons; LB, UB & UB2 Indicators

Type of Change:

- Engineering
 Part Number
- □ Product ☑ Appearance

I. The location of production will change for UB and UB2 Pushbuttons, LB, UB and UB2 Illuminated Pushbuttons, and LB, UB and UB2 Indicators from the China factory to the Philippines factory. The box in which the switches are packaged for shipping will read "PHILIPPINES FACTORY" instead of "CHINA FACTORY." The lot number on the side of the switch cases will have a dot mark above the second digit instead of the first digit. All of these modifications will apply to all UL/CSA approved standard and custom products.



Changes for LB, UB & UB2 Pushbuttons & Indicators

Example: UB215SK	Lot Number	Shipping Box
Before Changes	Lot Number Above First Digit	"CHINA FACTORY" printed on side of box
After Changes	Lot Number Above Second Digit	"PHILIPPINES FACTORY" printed on side of box

The following groups of products reflect the changes of production location, lot number marks and packaging, and include all UL approved standard and custom products:

UB Nonilluminated Pushbuttons

· LB Illuminated Pushbuttons

- UB Illuminated Pushbuttons
- UB2 Nonilluminated Pushbuttons
- UB2 Illuminated Pushbuttons
- LB Indicators
- UB Indicators
- UB2 Indicators

Notes

There are no changes to the switches' dimensions or specifications. The location of the Lot Number may vary depending on the part number. See website or contact the factory if more details are needed.

Effective Date

Changes to LB, UB and UB2 Pushbuttons, Illuminated Pushbuttons and Indicators will be effective October 2016.

NKK SWITCHES CO., LTD. http://www.nkk.com E-mail: nkkswitches@nkkswitches.co.jp

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031

Contact No. 272

Change Notice


Changes to UB & UB2 Pushbuttons; LB, UB & UB2 Iluminated Pushbuttons; LB, UB & UB2 Indicators

Type of Change:

- □ Engineering □
- □ Product
- Part NumberAppearance

2. UB and UB2 Nonilluminated Pushbuttons, and LB, UB and UB2 Illuminated Pushbuttons, all with UL approval, will have a change on the switch case for all standard and custom devices. Previously, the UL symbol appeared on the case with factory code 078. After the change, the code 080 will appear next to the UL symbol. The table below illustrates the modification.

LB, UB & UB2 Series



- LD Illuminated Pushbuttons, shap-in mount (does not include parter seal
- UB Illuminated Pushbuttons (does not include super bright bicolor LED)
- UB2 Illuminated Pushbuttons (does not include super bright Blue/Amber bicolor LED)
- LB Indicators
- UB Indicators (does not include super bright bicolor LED)
- UB2 Indicators (does not include super bright Blue/Amber bicolor LED)

Notes

For factory code or logo changes, there will be no revisions to the switches' dimensions or specifications. The location of the factory code or logo may vary depending on the part number. See website or contact the factory if more details are needed.

Effective Date

Changes to LB, UB and UB2 Pushbuttons, Illuminated Pushbuttons and Indicators will be effective October 2016.

NKK SWITCHES CO., LTD. http://www.nkk.com E-mail: nkkswitches@nkkswitches.co.jp

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031