Contact No. 319-A

Change Notice



Changes to Location & Production for Medium/High Capacity S30s & S40s Toggles

Τv	рe	of	Ch	ar	na	e:
·y	\sim	0.	0.1	u	.9	Ο.

□ Engineering□ Part Number□ Product☑ Appearance

Contact No. 319 was originally released September 2017. Since that time, NKK Switches has decided that Change 2 (page 2) will not be implemented, effective May 2018 (Contact No. 319-A). There are no modifications to Changes 1 and 3, which will be administered as indicated.

Changes for S30 & S40 Toggles

I. The location of production will change from the Japan factory to the Philippines factory for S30s and S40s S Series Toggles. The place of manufacture will no longer appear on the switches, and the logo will be updated. The lot number on the switch case will have a dot mark above the second digit, and the box in which the switches are packaged for shipping will read "PHILIPPINES FACTORY" instead of "JAPAN FACTORY." All of these revisions will apply to standard and custom products. Effected standard part numbers are listed below.

	Switch Case	Logo	Lot Number	Shipping Box
Before Changes	"JAPAN" on Switch Case	Older NKK Logo	Example of Lot Number	"JAPAN FACTORY" printed on side of box
After Changes	"JAPAN" on Switch Case Removed	NKK Logo Updated	Example of Lot Number with Dot Mark Above Second Digit	"PHILIPPINES FACTORY" printed on side of box

Notes

There are no changes to the switches' dimensions or specifications.

The location of logo or lot number on switch case may vary depending on the part number. Contact the factory if more details are needed.

Change 1: S30 Toggles				Change 1: S40 Toggles			
S31	S35	S31T	S31F	S41	S49	S41F	S42R
S32	S38	S32T	S32F	S42	S41T	S42F	S43R
S33	S39	S33T	S33F	S43	S42T	S43F	S48R
				S45	S43T	S41R	S49R
				S48			

Effective Date

Location and production changes for S30s and S40s Toggles will be effective August 2018.

NKK SWITCHES CO., LTD. http://www.nkk.com E-mail: nkkswitches@nkkswitches.co.jp

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031

Contact No. 319-A

Change Notice



Identification Plate Change for S30s & S40s Toggles

Type of Change: ☐ Engineering ☐ Product	☐ Part Number ☑ Appearance	The following Change 2 of Contact No. 319, released September 2017, will be executed. This decision is effective upon the May 2018 release of Conta No. 319-A. Changes 1 and 3 will be administered as initially announced.				
		2. The S30s and S40s Toggles will have an update to the method of display for part numbers on the switch body. Previously, they were displayed on identification plates, which will be changed to laser application. The revision applies to standard, custom and UL/CSA approved products. Effected standard part numbers are on the table at the bottom of page 1.				
		l doublification				

Identification						
Before Change	After Change	Revision Rescinded				
Part Number Displayed on Identification Plate	Part Number Displayed by Laser Marking	This change has been updated 05/11/18 and will not take place. Part Number will continue to be displayed on Identification Plate, and not convert to Laser Marking.				

UL Factory Code Added for S30s & S40s Toggles

	Before Change	UL Factory Code Change After Change				
□ Engineering□ Product	□ Part Number☑ Appearance	case to include both standard and custom devices. Previously, the UL symbol appeared on the case without a factory code. After the change, the code 080 will appear next to the UL symbol, as shown here. Effected standard part numbers are on the table below.				
Type of Change:		3. The UL approval for S30s and S40s Toggles will have a change on the switch				

UL Approval & No Factory Code



UL Approval & Factory Code Added



Notes

There are no changes to the switches' dimensions or specifications.

The location of the UL code on switch case may vary depending on the part number.

Contact the factory if more details are needed.

Changes 1 & 3: S30 Toggles					Changes 1 & 3: S40 Toggles			
S31/U	S35/U	S31T/U	S31F/U	S41/U	S49/U	S41F/U	S42R/U	
S32/U	S38/U	S32T/U	S32F/U	S42/U	S41T/U	S42F/U	S43R/U	
S33/U	S39/U	S33T/U	S33F/U	S43/U	S42T/U	S43F/U	S48R/U	
				S45/U	S43T/U	S41R/U	S49R/U	
				S48/U				

Effective Date

The identification plate and UL factory code changes for S30s and S40s Toggles will be effective August 2018. The Identification Plate Change #2 will **not** take place effective May 11, 2018, with release of Contact No. 319-A.

NKK SWITCHES CO., LTD. http://www.nkk.com E-mail: nkkswitches@nkkswitches.co.jp

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031